

100 East Diamond Ave. Hazleton, Pennsylvania 18201-5241 800-424-3596 570-454-3596 • Fax: 570-459-1752

Material Safety Data Sheet

U.S. Department of Labor

May be used to comply with

OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

Occupational Safety and Health Administration

(Non-Mandatory Form) Form Approved OMB No. 1218-0072

1	IDENTITY (As Used on Label and List)
	SARGENT WASHABLE GLITTER PAINT

Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.

Section I

Manufacturer's Name Sargent Art, Inc.	Emergency Telephone Number 570-454-3596 Telephone Number for Information 570-454-3596		
Address (Number, Street, City, State, and ZIP Code)			
	Date Prepared	7-26-2002	
100 E Diamond Avenue			
Hazleton PA 18201	Signature of Preparer (optional)	

Section II - Hazard Ingredients/Identity Information

Hazardous Components (Specific

Chemical Identity, Common Name(s))

ALL CP/AP PRODUCTS ARE CERTIFIED BY A NATIONAL RECOGNIZED AUTHOR-

ITY ON TOXICOLOGY ASSOCIATED WITH A LEADING UNIVERSITY TO CONTAIN

NO KNOWN TOXIC MATERIALS IN SUFFI CIENT QUANTITIES TO BE

INJURIOUS TO THE HUMAN BODY EVEN _ IF INGESTED.

CONFORMS TO ASTM-D 4236.

Section III - Physical/Chemical Characteristics

Bolling Point NOT AP	PLICABLE	Specific Gravity (H ₂	0 = 1)	N/A
Vapor Pressure (mm Hg.)	Melting Point N/A			
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A	<u> </u>
Solubility in Water		Water Soluable - Water Dispersible		
Appearance and Odor Section IV - Fire and Explosion Hazard Da		Various Colors - Essentially Odorless		
Flash Point (Method Used)	N/A	Flammable Limits NONE	LEL NONE	UEL NONE
Extinguishing Media Special Fire Fighting Procedures		CARBON DIOXIDE, SELF-CONTAINED E APPARATUS		
Unusual Fire and Explosion Hazards		NONE		



100 East Diamond Ave. Hazleton, Pennsylvania 18201-5241 800-424-3596 570-454-3596 • Fax: 570-459-1752

Stability	Unstable Conditions to Avoid			
	Stable X None Known			
Incompatibility (Materials to Avoid)	Strong oxidizers and acids			
Hazardous Decomposition or Byproducts				
Hazardous May Occur Polymerization Will Not Occur X	Conditions to Avoid None Known			
Section VI - Health Hazard Data				
Route(s) of Entry: Inhalation? Possible	Skin? N/A Ingestion? Possible			
Health Hazards (Acute and Chronic)				
This product is certified to contain no toxic or injurious to humans or to cause	materials in sufficient quantities to be acute or chronic health problems.			
Carcinogenicity: NTP? None	IARC Monographs? N/A OSHA Regulated? No			
Signs and Symptoms of Exposure	None Known			
Medical Conditions Generally Aggravated by Exposure	None Known			
Emergency and First Aid Procedures	If ingested, do not induce vomiting, call physician.			
Section VII - Precautions for Safe Handlin	g and Use			
Steps to Be Taken in Case Material Is Released or Spilled	Sweep into container and dispose of according to local regulations.			
Waste Disposal Method	In accordance with local regulations.			
Precautions to Be taken in Handling and	Keep in cool, dry area.			
Storing Other Precautions	None Known			
Section VIII - Control Measures				
Respiratory Proctection (Specify Type)	Not Required.			
Ventilation Local Exhaust	Not Required Special None			
Mechanical (General)	Not Required Other None			
Protective Gloves	Not Required Eye Protection Not Required			
Other Protective Clothing or Equipment Work/Hygienic Practices	Not Required Clean, safe work practices			
Page	2			

Post-it* Fax Note 7671	Dale - 26-06 pages 2
To Brenda	From Slaine
Co./Dept. Ch. Sper.	Co. Largent art
Phone 1920 - 882-5905	Phone # 570-454- 3596
Fax # 920-882-448	Fax 5-70-459-1752